


SHOWMASTER FAT SSS 0263170/530

WIRING DIAGRAM



SHOWMASTER FAT SSS(FLAME ASH TOP) 0263170/530

SWITCH & CONTROL FUNCTION

5 WAY SWITCH POSITION					
					← 5WAY SWITCH POSITION
V&T	V&T	V&T	V&T	V&T	← TONE CONTROL
					← NECK PICKUP
					← MIDDLE PICKUP
					← BRIDGE PICKUP
	← PICKUP IS ON				← PICKUP IS OFF

